

Bathing Water Quality for Other Monitored Waters in 2023

Likely Classifications for all other monitored bathing waters based on monitoring data for the period 2020 to 2023

Local authority/bathing water	Water Quality (2020-2023)	Number of samples over 4 years
Carlow County Council		
River Barrow Clashganny	Meets Minimum Standard	26
River Barrow Bagenalstown	Meets Minimum Standard	26
Cork County Council		
Ballynamona Strand	Highest Quality	21
Ballyrisode	Highest Quality	20
Cadogans Strand, Schull	Highest Quality	22
Dooneen Pier	Highest Quality	23
Galley Cove	Highest Quality	20
Garnish	Highest Quality	20
Inch	Highest Quality	20
Oileán Chléire	Highest Quality	22
Oysterhaven	Generally Good Quality	25
Red Strand	Highest Quality	21
Ring (Greenlands Strand)	Highest Quality	20
Rocky Bay	Highest Quality	21
Shanagarry beach (Ardnahanich)	Highest Quality	21
Silver Strand, Sherkin Island	Highest Quality	20
Dublin City Council		
Half Moon	Highest Quality	80
North Bull Wall	Below Minimum Standard	80
Shelley Banks	Below Minimum Standard	80
Dun Laoghaire Rathdown County Council		
Dun Laoghaire Baths	Highest Quality	19
Fingal County Council		
Malahide Beach	Generally Good Quality	44
Galway County Council		
An Trá Mór, Gorumna Island	Highest Quality	21
Dog's Bay, Roundstone	Highest Quality	21
Dumhach	Highest Quality	19
East End Inisbofin	Highest Quality	20
Esker, Banagher	Highest Quality	17
Glassilaun, Killary	Highest Quality	20
Mannin Bay, Ballyconneely	Highest Quality	17
Omey Island Strand	Highest Quality	20
Renvyle	Highest Quality	19
Trá na Reilige, An Cheathrú Rua	Highest Quality	23
Trá Poll na gCaorach Inis Oirr	Highest Quality	20
Kerry County Council		
Béal Bán	Highest Quality	32
Cromane	Highest Quality	29
Derrymore	Generally Good Quality	23
Littor Beach	Highest Quality	29

Bathing Water Quality for Other Monitored Waters in 2023

Likely Classifications for all other monitored bathing waters based on monitoring data for the period 2020 to 2023

Local authority/bathing water	Water Quality (2020-2023)	Number of samples over 4 years
Reenroe	Highest Quality	29
Waterville Town Beach	Highest Quality	31
Mayo County Council		
Cross Beach, Belmullet	Highest Quality	24
Portacloy Beach	Highest Quality	25
Srah Beach	Highest Quality	24
Termon Beach	Highest Quality	24
Tránaun Beach, Inishturk	Highest Quality	23
Meath County Council		
Mornington	Highest Quality	26
Tipperary County Council		
Lough Derg - Castlough	Highest Quality	20
Lough Derg - Dromineer	Highest Quality	20
Lough Derg - Skehena	Highest Quality	20
Lough Derg - Terryglass	Highest Quality	20
Lough Derg - Youghal Quay	Highest Quality	20
Waterford City and County Council		
Annestown	Highest Quality	21
Ballyquin	Highest Quality	20
Ballyvooney	Generally Good Quality	22
Boatstrand	Generally Good Quality	22
Curragh	Highest Quality	20
Goat Island	Highest Quality	21
Guillamene	Highest Quality	20
Kilfarrassey	Highest Quality	21
Newtown Cove	Highest Quality	20
Stradbally	Generally Good Quality	20
Whiting Bay	Highest Quality	20
Woodstown	Highest Quality	21
Wexford County Council		
Baginbun	Highest Quality	56
Ballyhealy	Highest Quality	60
Booley Bay	Highest Quality	62
Cahore	Highest Quality	62
Cullenstown	Highest Quality	60
Culletons Gap	Highest Quality	60
Grange	Highest Quality	61
Kilmore Quay Small Beach	Generally Good Quality	65
Old Bawn	Highest Quality	60
Rosslare Harbour	Highest Quality	43
St Helens Bay	Highest Quality	63
Wicklow County Council		
Arklow South Beach	Highest Quality	25

Bathing Water Quality for Other Monitored Waters in 2023

Likely Classifications for all other monitored bathing waters based on monitoring data for the period 2020 to 2023

Local authority/bathing water	Water Quality (2020-2023)	Number of samples over 4 years
Kilcoole Beach	Highest Quality	23
Murrough Beach	Highest Quality	22
South of Bray Harbour	Generally Good Quality	30
The Cove, Arklow	Meets Minimum Standard	31
The Cove, Greystones	Highest Quality	25
Wicklow Harbour Bathing Area	Meets Minimum Standard	27